

NAME Salvers, Douglas

MAP NO.: _____

DESCRIPTION West Dante int in lot 8DISTRICT Kenady

MAIN BUILDING									
USE	CONSTRUCTION		EXTERIOR FINISH		INTERIOR FINISH		ROOFING	GENERAL FEATURES	
Dwelling	Wood	Frame	Wood	Siding	Plaster		Comp. Sh.	Year Built	Bathrooms
Store	Steel	Frame	Brick		Wall Board		Slate	No. Rooms	Basement
Service Station	Tile-C.	Blk	Asb-wood	shing.	Ceiled		Asbestos	No. Stories	Fireplace
Garage	Brick		C. Block		Panel		Metal	Foundation	Stoves
Factory	Mill		Stucco		Tile		Tar&Grav.	Floors	Cent. Heat
	Reinf. Conc.							Porch	Floor Fur.
X	X	=	CU. FT.		UNIT FACTOR		TOTAL	Physical Depreciation or Obsolescence	APPRAISED VALUE
			SQ. FT.				=	=	\$

OUT BUILDINGS					
USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS	
Garage <i>Carport</i> ✓	<i>Cement</i>	<i>Fair</i>	<i>15x24 = 360</i>	<i>\$ @ 2.</i>	
Barn					
Chicken House					
Tenant House					
Misc. Bldg. ✓	<i>C/A</i>	<i>Fair</i>	<i>10x15 = 150</i>	<i>\$ @ 4.</i>	

Total Appraised Value All Improvements \$ 1300

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	<i>Lot</i>	<i>F.V.</i>	<i>4000 2000</i>					
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL	<i>Int. in Lot 8</i>		\$					

Total Appraised Value All Lands \$

Notes: *No building TRAILER on the lot*

RECAPITULATION			
	APPRAISED VALUE		ASSESSED VALUE
Land	\$	<i>4000 2000</i>	\$ <i>1000</i>
Bldgs.	\$	<i>1300</i>	\$
TOTAL	\$		\$

Right of 627