

NAME Salvers, Paul H & Shirley

MAP NO.: _____

DESCRIPTION McClure River .20DISTRICT Kenady

MAIN BUILDING													
USE		CONSTRUCTION		EXTERIOR FINISH		INTERIOR FINISH		ROOFING		GENERAL FEATURES		PLUMBING & HEATING	
Dwelling	✓	Wood Frame	✓	Wood Siding		Plaster		Comp. Sh.		Year Built		Bathrooms	✓ Shower
Store	✓	Steel Frame		Brick		Wall Board	✓	Slate		No. Rooms	6+1	Basement	Father NO
Service Station		Tile-C. Blk		Asb-wood shing.	✓	Ceiled		Asbestos		No. Stories	2	Fireplace	
Garage		Brick		C. Block		Panel		Metal	✓	Foundation	5	Stoves	✓
Factory		Mill		Stucco		Tile		Tar&Grav.		Floors		Cent. Heat	✓ O.I.F.
		Reinf. Conc.								Porch		Floor Fur.	
x 36 x 50 = 1800				CU. FT.		UNIT FACTOR		TOTAL		Physical Depreciation or Obsolescence		APPRAISED VALUE	
				SQ. FT.		17 15		=				= \$ 21600 - 21000	

OUT BUILDINGS					
USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS	
Garage					
Barn					
Chicken House					
Tenant House					
Misc. Bldg.					

Total Appraised Value All Improvements \$

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	.2	FV	6000 4000					
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL	0.2		\$					

Total Appraised Value All Lands \$

Notes:			RECAPITULATION		
			APPRAISED VALUE		ASSESSED VALUE
			Land	\$ 6000 4000	\$ 4000
			Bldgs.	\$ 21600	\$ 21600
			TOTAL	\$ 27600	\$ 27600