

NAME Farmer, Woodrow & Gladys

MAP NO.: _____

DESCRIPTION Mullins Ridge 1.63DISTRICT Willis

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat
DW ✓	Reinf. Conc.				Porch	Floor Fur.

x 24 x 40 = 960

CU. FT.
SQ. FT.

UNIT FACTOR

TOTAL

Physical Depreciation
or Obsolescence

APPRAISED VALUE

(2) \$ 14 700

OPch- 2x18=126 # 3. = 376

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage CP ✓			12x24 = 288 # 3. = 864 (incl. alpen)	
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

LAND

				Lots			
No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site 115	1.63	FV 4260400					
2. Residential							
3. Agricultural							
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
TOTAL		\$					

Total Appraised Value All Lands \$

Notes: L of 607

				RECAPITULATION		
				APPRAISED VALUE	ASSESSED VALUE	
Land	\$	4200	11000	\$		
Bldgs.	\$	14700		\$		
TOTAL	\$	4400	18700	\$		