

NAME Gayle, Robert Lee and LynnMAP NO.: XDESCRIPTION Rt. 2 Box 14 Clintwood, VADISTRICT Willis

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat
	Reinf. Conc.				Porch	Floor Fur.
$\begin{matrix} X & X \\ 28 & \times & 60 \\ \hline 1680 \end{matrix}$			CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
			SQ. FT.	22	=	=
						APPRaised VALUE
						\$ 37,500

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage			28 X 20	12
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$ 43,750

LAND

Lots

	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	1		4,500					
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$					

Total Appraised Value All Lands \$

Notes:	RECAPITULATION		
	APPRaised VALUE		ASSESSED VALUE
	Land	\$ 4,500	\$
	Bldgs.	\$ 43,750	\$
	TOTAL	\$ 48,250	\$