

NAME Gilbert, Charlie & Tilda

MAP NO.: \_\_\_\_\_

DESCRIPTION Cane Branch 13.67 10.17 8.17

DISTRICT Willis

BLOCK \_\_\_\_\_ HOUSE NO. \_\_\_\_\_

**MAIN BUILDING**

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING	
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	Comp. Sh. ✓	Year Built	Bathrooms <u>NO</u>	
Store	Steel Frame	Brick <u>siding</u> ✓	Wall Board	✓ Slate	No. Rooms <u>5</u>	Basement <u>PART.</u>	
Service Station	Tile-C. Blk	Ash-wood shing.	Ceiled	Asbestos	No. Stories ✓	Fireplace ✓	
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves ✓	
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat	
	Reinf. Conc.				Porch ✓	Floor Fur.	
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRAISED VALUE
			SQ. FT.		=		<u>\$200 800</u>

**OUT BUILDINGS**

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				
<u>store</u>	<u>FR</u>	<u>Poor</u>	<u>Small</u>	

Total Appraised Value All Improvements \$ 1100

**LAND**

USE	No. Acres	Value Per Acre	TOTAL	Lots				Appraised Value
				Lot No.	Zoning	Size	Front Ft. Factor	
1. Tillable								
2. Pasture								
3. Timber								
4. Cut Over								
5. Marsh - Mountain								
6. Commercial								
7. Industrial								
8. Mineral			<u>800</u>					
TOTALS	<u>13.67</u>		<u>\$800</u>					

Total Appraised Value All Lands \$ \_\_\_\_\_

Notes: Below Clayton Center  
last house behind  
Church

BUILDING PERMITS					
No.	Type	Date	% of Comp	Final A.	

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ <u>800</u>	\$ <u>80</u>
Bldgs.	\$ <u>1100</u>	\$ <u>110</u>
TOTAL	\$ <u>1900</u>	\$ <u>190</u>

