

NAME Hall, Dorothy

MAP NO.: _____

DESCRIPTION McClure River 1.50DISTRICT Willis

BLOCK _____ HOUSE NO. _____

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms <u>20</u>
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms <u>4</u>	Basement <u>no</u>
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories <u>1</u>	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves <u>✓</u>
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat
	Reinf. Conc.				Porch	Floor Fur.
X	X	=	CU. FT. SQ. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
					=	—
						APPAISED VALUE
						\$ <u>no value</u>

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

LAND

Lots

USE	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Tillable								
2. Pasture								
3. Timber								
4. Cut Over								
5. Marsh - Mountain								
6. Commercial								
7. Industrial								
8. Mineral								
TOTALS	<u>1.5</u>		<u>\$ 400 200</u>					

Total Appraised Value All Lands \$ 200Notes: Deeded to - Jess Taylor

BUILDING PERMITS

No.	Type	Date	% of Comp	Final A.
<u>Taylor</u>				

RECAPITULATION

	APPRAISED VALUE	ASSESSED VALUE
Land	\$ <u>200</u>	\$ <u>20</u>
Bldgs.	\$	\$
TOTAL	\$	\$

9186

[illegible]

REMARKS

MAP NO.

DESCR. McClure River

SUBD. 1.

LOT _____ BLOCK _____ SECTION _____

ACREAGE 1.50

[illegible]