

NAME Hill, Leon & Bertha J.

MAP NO.: _____

DESCRIPTION Rt. 1 Clintwood, VADISTRICT Willis

MAIN BUILDING														2
USE		CONSTRUCTION		EXTERIOR FINISH		INTERIOR FINISH		ROOFING		GENERAL FEATURES		PLUMBING & HEATING		
Dwelling		Wood Frame		Wood Siding		Plaster		Comp. Sh.		Year Built		Bathrooms		
Store		Steel Frame		Brick		Wall Board		Slate		No. Rooms		Basement		
Service Station		Tile-C. Blk		Asb-wood shing.		Ceiled		Asbestos		No. Stories		Fireplace		
Garage		Brick		C. Block		Panel		Metal		Foundation		Stoves		
Factory		Mill		Stucco		Tile		Tar&Grav.		Floors		Cent. Heat		
		Reinf. Conc.								Porch		Floor Fur.		
X		X	=	CU. FT.		UNIT FACTOR		TOTAL		Physical Depreciation or Obsolescence		APPRaised VALUE		
				SQ. FT.				=		=		\$		

OUT BUILDINGS					
USE		CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage					
Barn					
Chicken House					
Tenant House					
Misc. Bldg.					

Total Appraised Value All Improvements \$

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site								
2. Residential								
3. Agricultural	.20	FV	100					
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$					

Total Appraised Value All Lands \$

Notes: (in yard.)		RECAPITULATION		
		APPRAISED VALUE		ASSESSED VALUE
		Land	\$ 100	\$
		Bldgs.	\$	\$
		TOTAL	\$ 100	\$