

2

[illegible]

NAME Hughes, Harold & WifeMAP NO.: XDESCRIPTION Yates Gap 1.0DISTRICT Willis

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar & Grav.	Floors	Cent. Heat
	Reinf. Conc.	<i>Alu.</i>			Porch	Floor Fur.
$\begin{matrix} X & X & = \\ 24 & 41 & = \end{matrix}$			CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
			960	12	=	=
			8Q. FT.			
						\$ 14,500

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

LAND

				Lots			
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor
1. Bldg. Site	1		5,000				
2. Residential							
3. Agricultural							
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
TOTAL			\$				

Total Appraised Value All Lands \$

Notes:

				RECAPITULATION		
					APPRAISED VALUE	ASSESSED VALUE
				Land	\$ 5,000	\$
				Bldgs.	\$ 14,500	\$
				TOTAL	\$ 19,500	\$