

NAME Lyall, Palmer C. & Zetta A.
 DESCRIPTION Mullins Ridge 3,

MAP NO.: _____
 DISTRICT Willis

BLOCK _____ HOUSE NO. _____

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEAT
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	Comp. Sh. ✓	Year Built 77	Bathrooms 2
Store	Steel Frame	Brick ✓	Wall Board ✓	Slate	No. Rooms 6	Basement FULL
Service Station	File-C. Bk	Ash-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace
Garage	Brick	C. Block	Panel ✓	Metal	Foundation 5	Stoves
Factory	Mill	Stucco	Tile	Tar & Grav.	Floors	Cent. Heat ELEC
	Reinf. Conc.				Porch	Floor Fur.
$26 \times 42 = 1092$			CU. FT. SQ. FT.	UNIT FACTOR 10.00	TOTAL = 10920 - 75%	Physical Depreciation or Obsolescence
						APPRaised VALU \$ 8,200

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$ 8,200

LAND

USE	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appra
1. Tillable								
2. Pasture								
3. Timber								
4. Cut Over								
5. Marsh - Mountain								
6. Commercial								
7. Industrial								
8. Mineral			200					
TOTALS	3.		200					

Total Appraised Value All Lands \$ 200

Notes: No Bldg Join Home tract

BUILDING PERMITS

No.	Type	Date	% of Comp	Final A.

RECAPITULATION

	APPRAISED VALUE	ASSESSED V
Land	\$ 200	\$ - 20
Bldgs.	\$ 8200	\$ 820.
TOTAL	\$ 8400	\$ 840

MAP NO.

DESCR. Mullins Ridge

SUBD.

LOT.

BLOCK

SEC

ACREAGE

3.

REMARKS