

[illegible]

REMARKS

FROM: Auty Rose

MAP NO. _____ 2

DESCR. Mullisn Ridge

SUBD.

LOT _____ BLOCK _____ SECTION _____

ACREAGE 0.30[illegible]

NAME Arthur Moore, Arbutu & Nola

MAP NO.: _____

DESCRIPTION Mullins Ridge ~~2-2~~ .3DISTRICT Willis

MAIN BUILDING <i>VH 3:45 1/16/77</i> <i>Z</i>													
USE		CONSTRUCTION		EXTERIOR FINISH		INTERIOR FINISH		ROOFING		GENERAL FEATURES		PLUMBING & HEATING	
Dwelling	✓	Wood Frame	✓	Wood Siding	✓	Plaster		Comp. Sh.	✓	Year Built		Bathrooms	✓
Store		Steel Frame		Brick		Wall Board		Slate		No. Rooms		Basement	<i>NO</i>
Service Station		Tile-C. Blk		Asb-wood shing.		Ceiled		Asbestos		No. Stories	<i>1</i>	Fireplace	
Garage		Brick		C. Block		Panel		Metal	✓	Foundation	<i>S</i>	Stoves	
Factory		Mill		Stucco		Tile		Tar&Grav.		Floors		Cent. Heat	
		Reinf. Conc.								Porch		Floor Fur.	
X		X		=		CU. FT.		UNIT FACTOR		TOTAL		Physical Depreciation or Obsolescence	
						SQ. FT.				=		=	
												<i>FV \$ 5000 5000</i>	

OUT BUILDINGS					
USE		CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage					
Barn					
Chicken House					
Tenant House					
Misc. Bldg.					

Total Appraised Value All Improvements \$

LAND				Lots			
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Appraised Value
1. Bldg. Site	<i>.3</i>	<i>FV</i>	<i>3000 2000</i>				
2. Residential							
3. Agricultural							
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
TOTAL			\$				

Total Appraised Value All Lands \$

Notes: <i>Rj 614</i>				RECAPITULATION			
					APPRAISED VALUE		ASSESSED VALUE
				Land	\$	<i>3000 2000</i>	\$
				Bldgs.	\$	<i>8000 5000</i>	\$
				TOTAL	\$	<i>11000 7000</i>	\$