

NAME Mullins, Alcieberry & I JoleneMAP NO.: XDESCRIPTION Cane Creek 8.DISTRICT Willis

MAIN BUILDING

2

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms 4	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories 1	Fireplace
Garage	Brick	C. Block	Panel	Metal ✓	Foundation 5	Stoves
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat
	Reinf. Conc.				Porch	Floor Fur.
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
			SQ. FT.		=	=
						APPRaised VALUE
						FV \$ 7000 3000

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

LAND

Lots

	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	1	FV	1000					
2. Residential								
3. Agricultural	7	200 250	1800					
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$ 2800					

Total Appraised Value All Lands \$

Notes:

RECAPITULATION

	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 2800	\$
Bldgs.	\$ 3000	\$
TOTAL	\$ 5800	\$