

NAME Mullins, Buddy & Linda

MAP NO.: _____

DESCRIPTION Cutter's Branch 20.DISTRICT Willis

MAIN BUILDING

5

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar & Grav.	Floors	Cent. Heat
	Reinf. Conc.				Porch	Floor Fur.

X	26	X	44	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRAISED VALUE
				sq. ft.				\$ 20,000 16,000

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.	7	Exterior		800

Total Appraised Value All Improvements \$ 16,800

LAND

Lots

No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	1	2500					
2. Residential							
3. Agricultural	12	500					
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
TOTAL		\$ 8200					

Total Appraised Value All Lands \$

Notes:

RECAPITULATION

	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 5,200	\$
Bldgs.	\$ 16,800	\$
TOTAL	\$ 22,000	\$