

NAME Mullins, ~~Larry & Dorothy~~ ^{Edward L.}

MAP NO.: _____

DESCRIPTION Bartlick ± .30DISTRICT Sandlick

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	✓ Wood Frame	✓ Wood Siding	✓ Plaster	Comp. Sh.	Year Built	Bathrooms
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar & Grav.	Floors	Cent. Heat
	Reinf. Conc.				Porch	Floor Fur.
X	X	=	CU. FT. SQ. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
					=	=
						APPRaised VALUE
						\$ NV

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS	
Garage					
Barn					
New Chicken House			20 x 32	640 x 20	12,800
Tenant House	✓ 1sty 9/8 4-rm.	No bath	Stone Ht	FV	2000
Misc. Bldg.					

Total Appraised Value All Improvements \$ 12000

LAND

LAND				Lots			
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor
1. Bldg. Site	30	FV	3000				
2. Residential							
3. Agricultural	.30	FV	200				
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
TOTAL			\$				

Total Appraised Value All Lands \$

Notes:	RECAPITULATION		
		APPRaised VALUE	ASSESSed VALUE
	Land	\$ 2000	\$ 2000
	Bldgs.	\$	\$
	TOTAL	\$ 2000	\$