

NAME Mullins, Fitzhugh etals

MAP NO.: _____

DESCRIPTION Holly Creek 1839 sq. ft.DISTRICT Willis

MAIN BUILDING

USE		CONSTRUCTION		EXTERIOR FINISH		INTERIOR FINISH		ROOFING	GENERAL FEATURES		PLUMBING & HEATING	
Dwelling		Wood Frame		Wood Siding		Plaster		Comp. Sh.	Year Built		Bathrooms	
Store	✓	Steel Frame		Brick		Wall Board		Slate	No. Rooms	2	Basement	
Service Station		Tile-C. Blk	✓	Asb-wood shing.		Ceiled		Asbestos	No. Stories		Fireplace	
Garage		Brick		C. Block	✓	Panel		Metal	Foundation		Stoves	
Factory		Mill		Stucco		Tile		Tar&Grav.	Floors		Cent. Heat	
		Reinf. Conc.				C.B.I.K.		Tile	Porch		Floor Fur.	
X 2400 X =				CU. FT.	UNIT FACTOR		TOTAL	Physical Depreciation or Obsolescence		APPRAISED VALUE		
				SQ. FT.	16		=			\$16,100		

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

Lots

LAND

LAND				Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
No. Acres	Value Per Acre	TOTAL						
1. Bldg. Site	101	5,000						
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$					

Total Appraised Value All Lands \$

Notes:

RECAPITULATION

APPRAISED VALUE		ASSESSED VALUE
Land	\$ 5,000	\$
Bldgs.	\$	\$
TOTAL	\$ 5,000	\$