

NAME Mullins, Radford & WifeMAP NO.: XDESCRIPTION Bartley Branch 2.32DISTRICT Willis

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar & Grav.	Floors	Cent. Heat
	Reinf. Conc.	<i>Alum</i>			Porch	Floor Fur.
$24 \times 36 \times = 864$			CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
			SQ. FT.	<i>20</i>	$=$	$=$
						APPRAISED VALUE
						$\$17,300$

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

LAND

				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	<i>1</i>		<i>4,000</i>					
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other	<i>1.32</i>	<i>500</i>	<i>700</i>					
TOTAL			$\$4,700$					

Total Appraised Value All Lands \$

Notes:			RECAPITULATION		
				APPRAISED VALUE	ASSESSED VALUE
			Land	$\$4,700$	\$
			Bldgs.	$\$17,300$	\$
			TOTAL		