

SLUSS CLINE  
RT 3 BOX 398  
CLINTWOOD VA

24228

DATE RECORDED  
DEED OR WILL BOOK DB 0115 0135  
CONSIDERATION

DATE RECORDED  
DEED OR WILL BOOK  
CONSIDERATION

DATE RECORDED  
DEED OR WILL BOOK  
CONSIDERATION

DATE RECORDED  
DEED OR WILL BOOK  
CONSIDERATION

DATE RECORDED  
DEED OR WILL BOOK  
CONSIDERATION

CLASS 2  
ZONING  
DISTRICT 05


LEGAL DESCRIPTION  
MULLINS RIDGE  
3.8AC

Year	Area 1	Area 2	Area 3
1992			
1993			
1994	4,100	26,100	30,200
1995	4,100	26,100	30,200
1996			
1997			
1998	4,100	26,100	30,200
1999			
2000	4,100	26,100	30,200
2001			
2002			
2003			

BUILDING PERMITS

NO.	TYPE	DATE	% COM.	DATE FINAL	APPROVAL	APPROVAL

NOTES:



Dwelling	<input checked="" type="checkbox"/>	Comp. Sh.	<input checked="" type="checkbox"/>	Wood Siding		Yr. Built	<u>60</u>	Remod.		Bsmt.	[ ] 2nd [ ]	Plaster		BATH(S)	1 Full 1/2 Bath(s)
		Slate		Brick		No. Stories			<u>1</u>	1st	<u>5</u> 3rd [ ]	Sheet rock	<input checked="" type="checkbox"/>	Modern Bath	<input type="checkbox"/> Modern Kitchen <input type="checkbox"/>
		Asbestos		Aeb. Wood Shg.		S. Level	<input type="checkbox"/>	S. Foyer	<input type="checkbox"/>	Total No. Bedrooms		Ceciled		Cent. Heat	<u>WOOD</u> A/C
		Metal		Cln. Block	<input type="checkbox"/> Stone <input type="checkbox"/>							Panel		Fir. or Wall Furnace	<input type="checkbox"/> Stove(s) <input type="checkbox"/>
Wood Frame	<input checked="" type="checkbox"/>	Tar & Grav.		Stucco	<input type="checkbox"/> Con. Block <input type="checkbox"/>	Crawl	<input type="checkbox"/>	Conc.	<input type="checkbox"/>	HW	<input checked="" type="checkbox"/> Pine <input type="checkbox"/> Carp. <input type="checkbox"/> Tile <input checked="" type="checkbox"/>	Unfinished			
Cin. Block		Tile		Aluminum	<input checked="" type="checkbox"/> Masonite <input type="checkbox"/>	Flers	<input type="checkbox"/>	Cin. Blk	<input checked="" type="checkbox"/>						
Steel Frame		Shakes		Storm Doors	<input type="checkbox"/> Storm Win. <input type="checkbox"/>	Slab	<input type="checkbox"/>	Brick	<input type="checkbox"/>	Disappearing Stairs		Gd.	<input type="checkbox"/> Fair <input checked="" type="checkbox"/> Poor <input type="checkbox"/> VP <input type="checkbox"/>	Number	<u>ND</u>

FR	900	32	28,800
Porch	200	8	1600
Carport	276	8	2208
Garage			
Cent. A/C			
Basement	450	6.5	2925
Bsmt. Finish			
Attic			
Fireplace(s)			
Heating			
Bath(s)			
Total			<u>35,533</u>
Factor			<u>.87</u>
Replacement			<u>30,914</u>

Gd.	<input type="checkbox"/>	Fair	<input checked="" type="checkbox"/>	Poor	<input type="checkbox"/>	VP	<input type="checkbox"/>				
Basmt. Finish		1/4	<input type="checkbox"/>	1/2	<input type="checkbox"/>	3/4	<input type="checkbox"/>	Full	<input type="checkbox"/>		
Attic		Walls	<input type="checkbox"/>	Fl.	<input type="checkbox"/>			Stone	<input type="checkbox"/>	Metal	<input type="checkbox"/>
YR.			<u>94</u>								
Dwelling											
FCP	12x22										
UGR	22x30										
WS	10x44										
Market Value All Improvements											
Market Value All Land											
TOTAL MARKET VALUE											
APRP.	<u>M5</u>	APRP.									
DATE	<u>2-15-94</u>	DATE									
CLASSIFICATION	<u>2</u>	ZONING									

Percentage	Depth	Square Footage	Unit Price	Value	Front Ft. Rate	TOTAL	ADJ.	TOTAL APPRAISAL	Unit Price	Depth Factor	Front Ft. Rate	TOTAL	ADJ.	IS TOTAL APPRAISAL

LEVEL	<input type="checkbox"/>	SLOPES UP	<input type="checkbox"/>	SLOPES DOWN	<input type="checkbox"/>
LOW	<input type="checkbox"/>	STEEP UP	<input type="checkbox"/>	STEEP DOWN	<input type="checkbox"/>

General Remarks: