

NAME Stanley, Viola

MAP NO.: _____

X

DESCRIPTION Brush Creek 9/1

DISTRICT Willis

2

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms 4	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories 1	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation 5	Stoves
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat
	Reinf. Conc.				Porch	Floor Fur.
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
			SQ. FT.		=	=
						APPRaised VALUE
						FV \$ 2500 5000

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$ 5000

LAND

	No. Acres	Value Per Acre	TOTAL	Lots			
				Lot No.	Zoning	Size	Front Ft. Factor
1. Bldg. Site	1	FV	2500 500				
2. Residential							
3. Agricultural	8 1/10	300	2600				
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
TOTAL			\$5100 4600				

Total Appraised Value All Lands \$

Notes:	RECAPITULATION		
		APPRAISED VALUE	ASSESSED VALUE
	Land	\$ 4600	\$
	Bldgs.	\$ 5000	\$
	TOTAL	\$ 9600	\$