

NAME Mullins, Paul & Wilhelmina

MAP NO.: _____

DESCRIPTION Orr Add. lot 53-54-55+ 56

DISTRICT Clintwood Corp.

MAIN BUILDING										
USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING				
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms	1 1/2			
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement	6			
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace				
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves				
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat	oil			
	Reinf. Conc.				Porch	Floor Fur.				
$30 \times 70 \times 11 = 23100$ $20 \times 70 = 1400$			CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRaised VALUE			
			SQ. FT.	28	=	=	\$ 39,500			

OUT BUILDINGS				
USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site				53			11	81.00
2. Residential				54				
3. Agricultural				55				
4. Commercial				56				
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$					

Total Appraised Value All Lands \$

Notes: _____	RECAPITULATION		
		APPRAISED VALUE	ASSESSED VALUE
	Land	\$ 8,000	\$
	Bldgs.	\$ 39,500	\$
	TOTAL	\$ 47,500	\$