

NAME Chandler, Guh Lindel & Maxine C.

MAP NO.: _____

X

DESCRIPTION McClure River 0.25

DISTRICT Ervington

MAIN BUILDING										
USE	CONSTRUCTION		EXTERIOR FINISH		INTERIOR FINISH		ROOFING	GENERAL FEATURES		PLUMBING & HEATING
Dwelling	<input checked="" type="checkbox"/>	Wood Frame	<input checked="" type="checkbox"/>	Wood Siding	<input checked="" type="checkbox"/>	Plaster	Comp. Sh.	<input checked="" type="checkbox"/>	Year Built	Bathrooms
Store		Steel Frame		Brick		Wall Board	Slate	No. Rooms	4	Basement
Service Station		Tile-C. Blk		Asb-wood shing.		Ceiled	Asbestos	No. Stories	1	Fireplace
Garage		Brick		C. Block		Panel	Metal	Foundation		Stoves
Factory		Mill		Stucco		Tile	Tar&Grav.	Floors		Cent. Heat
		Reinf. Conc.				<i>Paper</i>		Porch		Floor Fur.
X	X	=		CU. FT.		UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence		APPRAISED VALUE
				SQ. FT.			=	=		<i>24 \$ 5000 4000</i>

OUT BUILDINGS					
USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS	
Garage					
Barn					
Chicken House					
Tenant House					
Misc. Bldg.					

Total Appraised Value All Improvements \$

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site			<i>2000</i>					
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$					

Total Appraised Value All Lands \$

Notes: *of 635*
25.60

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 2000	\$
Bldgs.	\$ <i>5000 4000</i>	\$
TOTAL	\$ <i>7000 6000</i>	\$