

NAME Deel, Elvies & Cathleen

MAP NO.: _____

X

DESCRIPTION Rock Lick 110.50

DISTRICT Devinton

MAIN BUILDING									
USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING			
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	Comp. Sh. ✓	Year Built	Bathrooms	✓ Shower		
Store	Steel Frame	Brick	Wall Board ✓	Slate	No. Rooms	Basement	✓ half.		
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace			
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves	✓		
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat			
	Reinf. Conc.				Porch	Floor Fur.			
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRaised VALUE		
			SG. FT.		=	=	FY. \$ 5000		

OUT BUILDINGS					
USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS	
Garage					
Barn					
Chicken House					
Tenant House	✓ 1st fl FR, 4 rms, NO bath or bsmt, Stove				FV. 2000 2000
Misc. Bldg.	✓				FV. 200

Total Appraised Value All Improvements \$ ~~8200~~ 7200

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	2hs	1	FV. 5000 3000					
2. Residential								
3. Agricultural	109 1/2	20 250	21802 27400					
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$ 26400 24000 30400					

Total Appraised Value All Lands \$

Notes: R+L of 712

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 26500 24500	\$ 30400
Bldgs.	\$ 8000 1200	\$ 7200
TOTAL	\$ 33000 25500	\$ 37600