

NAME Barton, Verlin & Berra M.

MAP NO.: 178-189 B (A) 1067

x

DESCRIPTION Caney Ridge 0.56

DISTRICT Clintwood

2

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat
	Reinf. Conc.				Porch	Floor Fur.

12x7 x 35 x 26 = 734-91 CU. FT.
 663 SQ. FT.

UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRAISED VALUE
18+14+6	=	=	\$ 18700 / 15000

Por 7x13=91 5x5=25 @ 4

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage CP	Metal			FV 200
Barn				
Chicken House				
Tenant House				
Misc. Bldg.	Fr			FV 100

Total Appraised Value All Improvements \$ ~~19000~~ 15300

LAND

	No. Acres	Value Per Acre	TOTAL	Lots			
				Lot No.	Zoning	Size	Front Ft. Factor
1. Bldg. Site	Lot	FV	3500				
2. Residential							
3. Agricultural							
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
TOTAL			\$ 3500				

Total Appraised Value All Lands \$

Notes:		RECAPITULATION		
		APPRAISED VALUE	ASSESSED VALUE	
	Land	\$ 3500	\$	
	Bldgs.	\$ 15300	\$	
	TOTAL	\$ 18800	\$	