

NAME Meade, Arvil F. & Virgie E.

MAP NO.: _____

DESCRIPTION McClure Lot 20

DISTRICT Ervinton

MAIN BUILDING <i>Wh-11.00 2/23/77</i>									
USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING			
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms			
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement			
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace			
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves			
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat			
	Reinf. Conc.				Porch	Floor Fur.			
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRAISED VALUE		
			SQ. FT.		=	=	\$		

OUT BUILDINGS					
USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS	
Garage					
Barn					
Chicken House					
Tenant House					
Misc. Bldg.					

Total Appraised Value All Improvements \$

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site								
2. Residential	<i>Lot</i>	<i>FV</i>	<i>1000</i>					
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$ <i>1000</i>					

Total Appraised Value All Lands \$

Notes: *Beside home lot.*

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ <i>1000</i>	\$
Bldgs.	\$	\$
TOTAL	\$	\$