



NAME Mullins, Bobby R. & Peggy I.

MAP NO.: \_\_\_\_\_

DESCRIPTION Priest Fork 0.115

DISTRICT Sandlick Ervinton

MAIN BUILDING											
USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING					
Dwelling	✓ Wood Frame	Wood Siding	Plaster	Comp. Sh. ✓	Year Built	Bathrooms					
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms 6	Basement					
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories 1	Fireplace					
Garage	Brick	C. Block	Panel ✓	Metal	Foundation 5	Stoves					
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat	<i>Elect</i>				
	Reinf. Conc.	<i>Alum</i>			Porch	Floor Fur.					
x 26 x 44 = 1144			CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRaised VALUE				
			SQ. FT.	<i>2125</i>	=	=	<i>(R) \$ 23500 21200</i>				

*Patio 10x30 = 300 sq ft. = 600.*

OUT BUILDINGS					
USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS	
Garage					
Barn					
Chicken House					
Tenant House					
Misc. Bldg.					

Total Appraised Value All Improvements \$ *29200*

LAND				Lots			
No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	<i>Lot</i>	<i>FV</i>	<i>2000</i>				
2. Residential							
3. Agricultural							
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
<b>TOTAL</b>			<b>\$ 2000</b>				

Total Appraised Value All Lands \$

Notes: *Rof 682*

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ <i>2000</i>	\$ <i>2000</i>
Bldgs.	\$ <i>23500</i>	\$ <i>23500</i>
<b>TOTAL</b>	\$ <i>25500</i>	\$ <i>25500</i>