



NAME Mullins, Troy & Clarsie

MAP NO.: \_\_\_\_\_

x

DESCRIPTION McClure Lot 88

DISTRICT Ervinton

MAIN BUILDING

5/2/79

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	✓ Wood Frame	✓ Wood Siding	✓ Plaster	Comp. Sh.	✓ Year Built	Bathrooms
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms 5	Basement
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories 1	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat
	Reinf. Conc.				Porch	Floor Fur.
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence
			SQ. FT.		=	=
						APPRaised VALUE
						FY. \$ 7000 8000

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$ 8000

LAND

Lots

	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
				88				
1. Bldg. Site								
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$					2000

Total Appraised Value All Lands \$

Notes: below pg 63

RECAPITULATION

	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 5000 2000	\$
Bldgs.	\$ 9000 8000	\$
TOTAL	\$ 14000 10000	\$