



NAME Burton, Chas. H. & Delores

MAP NO. 100

DESCRIPTION West Dante Part of lots 3 & 4

DISTRICT Exington KENADY

MAIN BUILDING													
USE	CONSTRUCTION		EXTERIOR FINISH		INTERIOR FINISH		ROOFING		GENERAL FEATURES		PLUMBING & HEATING		
Dwelling	✓	Wood Frame	✓	Wood Siding	✓	Plaster		Comp. Sh.		Year. Built		Bathrooms	✓
Store		Steel Frame		Brick	✓	Wall Board		Slate		No. Rooms	5	Basement	
Service Station		Tile-C. Blk		Asb-wood shing.		Ceiled		Asbestos		No. Stories		Fireplace	
Garage		Brick		C. Block		Panel		Metal	✓	Foundation		Stoves	✓
Factory		Mill		Stucco		Tile		Tar&Grav.		Floors		Cent. Heat	
		Reinf. Conc.		Alum.	✓					Porch		Floor Fur.	
x 52x 62 = 1144				CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence		APPRaised VALUE				
				868					(\$ 9200 <del>10700</del> 9200)				

APPROX

OUT BUILDINGS				
USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	Lots	71.	3000 2100					
2. Residential								
3. Agricultural								
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL								

Total Appraised Value All Lands \$

Notes:	RECAPITULATION		
		APPRAISED VALUE	ASSESSED VALUE
	Land	\$ 3000 2100	\$
	Bldgs.	\$ 9200 <del>10700</del>	\$ 9200
	TOTAL	\$ 12200 8400	\$ 11200