

BURTON CHARLIE H
 HC67 BOX 140
 DANTE VA
 24237

DATE RECORDED *11/18/92*
 DEED OR WILL BOOK *DB 0292 0161*
 CONSIDERATION *Gift*

CLASS 2
 ZONING
 DISTRICT 03


LEGAL DESCRIPTION
 WEST DANTE
 PART OF LOTS 3 & 4
 170-B - 1519

	DATE RECORDED	
	DEED OR WILL BOOK	
	CONSIDERATION	
	DATE RECORDED	
	DEED OR WILL BOOK	
	CONSIDERATION	
	DATE RECORDED	
	DEED OR WILL BOOK	
	CONSIDERATION	
	DATE RECORDED	
	DEED OR WILL BOOK	
	CONSIDERATION	
	DATE RECORDED	
	DEED OR WILL BOOK	
	CONSIDERATION	

1992			
1993			
1994	2,500	13,700	16,200
1995	2,500	13,700	16,200
1996			
1997			
1998			
1999			
2000			
2001			
2002			
2003			

BIDDING PERMITS

NOTES:



Dwelling	<input checked="" type="checkbox"/>	Comp. Sh.	Wood Siding COMP SH	<input checked="" type="checkbox"/>	Yr. Built 30	Remod.	Bemt. [] 2nd []	Plaster	BATH(s) / Full [] 1/2 Bath(s) []
		State	Brick		No. Stories	1st [7] 3rd []	Sheet rock	Modern Bath <input type="checkbox"/> Modern Kitchen <input type="checkbox"/>	
		Asbestos	Asb. Wood Shg.		B. Level <input type="checkbox"/> S. Foyer <input type="checkbox"/>	Total No. Bedrooms	Ceiled	Cent. Heat Coal A/C <input type="checkbox"/>	
		Metal	Cin. Block <input type="checkbox"/> Stone <input type="checkbox"/>				Panel	Flt or Wall Furnace <input type="checkbox"/> Stove(s) <input type="checkbox"/>	
Wood Frame	<input checked="" type="checkbox"/>	Tar & Grav.	Stucco <input type="checkbox"/> Con. Block <input type="checkbox"/>		Crawl <input type="checkbox"/> Conc. <input type="checkbox"/>	HW <input type="checkbox"/> Pine <input type="checkbox"/> Carp. <input checked="" type="checkbox"/> Tile <input checked="" type="checkbox"/>	Unfinished		
Cin. Block		Tile	Aluminum <input checked="" type="checkbox"/> Masonite <input type="checkbox"/>		Riers <input type="checkbox"/> Cin. Blk. <input checked="" type="checkbox"/>			Number	
Steel Frame		Shakes	Storm Doors <input type="checkbox"/> Storm Win. <input type="checkbox"/>		Slab <input type="checkbox"/> Brick <input type="checkbox"/>	Disappearing Stairs	Gd. <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> VP <input type="checkbox"/>	Number Chimneys	
					Basement Size 25%	Attic Floor & Stairs		Brick [] C. Block []	
					Gd. <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> VP <input type="checkbox"/>	Basmt. Finish	1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> Full <input type="checkbox"/>	Attic <input type="checkbox"/> Walls <input type="checkbox"/> Fl. <input type="checkbox"/>	

13 ER 1237 30 37.710

YR. **94** YR. YR.

Dwelling					G		30,382	55%	13,472		
Porch	95	8	760								
Porch											
Carport											
Garage											
Cent. A/C											

Basement	314	6.5	2041	M & L	M & L	Market Value All Improvements	13,700
Bemt. Finish				DATE	DATE	Market Value All Land	2,500
Attic				APRP.	APRP.	Size	16,200
Fireplace(s)				MC		Cond.	
Heating				DATE	DATE	Not Home <input type="checkbox"/> Time	
Bath(s)				1-26-94		AM <input type="checkbox"/> PM <input type="checkbox"/>	
Total	40,511			CLASSIFICATION	ZONING	Agric.	
Factor	0.75			2		Hort.	
Replacement	30,382					Forest	
						Open Space	
						Totals	

Land Cost			
Bldg. Cost			
Sale Price			
Rent			
Expenses			
Net Rent			

CLASSIFICATION	ACRES	RATE	ADJ.	CLASSIFICATION	ACRES	RATE	ADJ.
Home Site				Home Site			
Public Water	Paved <input checked="" type="checkbox"/>						
Public Sewer	Gravel <input checked="" type="checkbox"/>						
Well	Dirt						
Spring	No Road						
Septic System	Curb & Gutter			Wasteland			
U. G. Utilities	Sidewalk			Wasteland			
		3 and 4				2500	

General Remarks:

LEVEL SLOPES UP SLOPES DOWN

LOW STEEP UP STEEP DOWN

BOARD REVIEW NOTES