

NAME Carlton, Lotta Robinson

MAP NO.: _____

DESCRIPTION Lick Fork 2.5 A.

DISTRICT Kenady

8

MAIN BUILDING									
USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING			
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built	Bathrooms			
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement			
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace			
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves			
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat			
	Reinf. Conc.				Porch	Floor Fur.			
8 x 20 + 20 x 50 = 1160			CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRAISED VALUE		
			8Q. FT.	8 10	=	=	(10) \$ 9200 (1160)		

(Built second floor)

OUT BUILDINGS					
USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS	
Garage					
Barn					
Chicken House					
Tenant House					
Misc. Bldg.					

Total Appraised Value All Improvements \$ 9200

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	1	F.V	15 1000					
2. Residential								
3. Agricultural	1 1/2	500 200	700 300					
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$ 2200 1300					

Total Appraised Value All Lands \$

Notes:	RECAPITULATION		
		APPRAISED VALUE	ASSESSED VALUE
	Land	\$ 2000 1300	\$
	Bldgs.	\$ 9200	\$
	TOTAL	\$ 11400 10500	\$