

| | | | | | | | |
|--------------------|---|--|--|---|--|---|--|
| Dwelling | <input checked="" type="checkbox"/> Comp. Sh. | <input checked="" type="checkbox"/> Wood Siding | Yr. Built 86 | Remod. | Bmnt. [] 2nd [] | Plaster | BATHS Full 1/2 Bath [] |
| | State | Brick | No. Stories | 1st [] 3rd [] | Sheet rock | Modern Bath [] Modern Kitchen [] | |
| | Asbestos | Asb. Wood Shg. | B. Level <input type="checkbox"/> S. Foyer <input type="checkbox"/> | Total No. Bedrooms | Cooled | Cent. Heat [] A/C [] | |
| Wood Frame | <input checked="" type="checkbox"/> Tar & Grav. | Cin. Block <input type="checkbox"/> Stone <input type="checkbox"/> | Stucco <input type="checkbox"/> Con. Block <input type="checkbox"/> | Crawl <input type="checkbox"/> Conc. <input type="checkbox"/> | HW <input type="checkbox"/> Pine <input type="checkbox"/> Carp. <input type="checkbox"/> Tile <input type="checkbox"/> | Unfinished | Flr. or Wall Furnace <input type="checkbox"/> Stove <input type="checkbox"/> |
| Cin. Block | Tile | Aluminum <input checked="" type="checkbox"/> Masonite <input type="checkbox"/> | Flers <input type="checkbox"/> Cin. Blk. <input type="checkbox"/> | Slab <input type="checkbox"/> Brick <input type="checkbox"/> | Disappearing Stairs | Gal. <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> VP <input type="checkbox"/> | Number |
| Steel Frame | Shakes | Storm Doors <input type="checkbox"/> Storm Win. <input type="checkbox"/> | Basement Size 00 | Attic Floor & Stairs | Basmt. Finish | 1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> Full <input type="checkbox"/> | Number Chimneys |
| 1st FR 96028 26880 | | Ed. <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> VP <input type="checkbox"/> | Attic <input type="checkbox"/> Walls <input type="checkbox"/> Fl. <input type="checkbox"/> | Stone <input type="checkbox"/> Metal <input type="checkbox"/> | Yr. 1994 | Yr. | Yr. |

| | | | | |
|-----------|---------------|-------|-----|-------|
| Dwelling | D- | 23785 | 3/6 | 22595 |
| Porch | WD 144 7 1008 | | | |
| Porch | FO 96 8 768 | | | |
| Carport | | | | |
| Garage | | | | |
| Cent. A/C | | | | |
| Basement | | | | |

| | |
|---|-------------------------------------|
| Owner | Market Value All Improvements 22600 |
| Make Year | Market Value All Land 3500 |
| Size Cond. | 26100 |
| Not Home <input type="checkbox"/> Time | |
| AM <input type="checkbox"/> PM <input type="checkbox"/> | |
| Agric. | |
| Hort. | |
| Forest | |
| Open Space | |
| Totals | |

| | | | |
|----------------|-----------|--------|------|
| Total | 28656 | | |
| Factor | .83 | | |
| Replacement | 23785 | | |
| CLASSIFICATION | 2 | ZONING | |
| DATE | 1-25-94 | DATE | |
| APRP | DR | APRP | |
| DATE | | DATE | |
| CLASSIFICATION | Home Site | ACRES | 1.58 |
| RATE | | ADJ. | 3500 |
| CLASSIFICATION | Wasteland | ACRES | 1.58 |
| RATE | | ADJ. | 3500 |

| | |
|-----------------|---|
| Public Water | <input checked="" type="checkbox"/> Paved |
| Public Sewer | Gravel <input checked="" type="checkbox"/> |
| Well | Dirt |
| Spring | No Road |
| Septic System | <input checked="" type="checkbox"/> Curb & Gutter |
| U. G. Utilities | Sidewalk |

General Remarks:

LEVEL SLOPES UP SLOPES DOWN

LOW STEEP UP STEEP DOWN

BOARD REVIEW NOTES