

## RECORD OF OWNERSHIP

COMPTON E B

BOX 45 Rt. 1 Box 545

DANTE VA 24237

C/O FRED COMPTON  
549 TUPELO DR

04778 MELBORNE, FL 32935

DATE  
RECORDEDDEED OR  
WILL BOOKCONSID-  
ERATION YR-  
SPDATE  
RECORDEDDEED OR  
WILL BOOKCONSID-  
ERATIONDATE  
RECORDEDDEED OR  
WILL BOOKCONSID-  
ERATIONDATE  
RECORDEDDEED OR  
WILL BOOKCONSID-  
ERATIONDATE  
RECORDEDDEED OR  
WILL BOOKCONSID-  
ERATION

## BUILDING PERMITS

NO.	TYPE	DATE	% COMP.	DATE FINAL	APPRAISAL	APPRAISAL

NOTES:

CLASS

2

ZONING

DISTRICT

03

LEGAL DESCRIPTION

SANDY RIDGE  
.22AC

YEAR

VALUE OF LAND

VALUE OF IMPROV.

TOTAL VALUE

AC

1986

100

—

100

1987

100

100

1988

100

—

100

1989

100

100

1990

100

100

1991

100

100

1992

1993

1994

1995

1996

1997

NOTES	MAIN BUILDING		ROOFING		EXTERIOR FINISH		GENERAL FEATURES		NUMBER OF ROOMS		INTERIOR FINISH		PLUMBING & HEATING				
	Dwelling		Comp. Sh.		Wood Siding		Yr. Built	Remod.	Bsmt. [ ]	2nd [ ]	Plaster		BATH(S)	Full 1/2 Bath(s)			
			Slate		Brick		No. Stories		1st [ ]	3rd [ ]	Sheet rock		Modern Bath [ ]	Modern Kitchen			
			Asbestos		Asb. Wood Shg.		S. Level [ ]	S. Foyer [ ]	Total No. Bedrooms		Ceciled		Cent. Heat	A/C			
	CONSTRUCTION		Metal		Cin. Block [ ]	Stone [ ]	FOUNDATION		FLOORS		Panel		Fir. or Wall Furnace [ ]	Stove(s) [ ]			
	Wood Frame		Tar & Grav.		Stucco [ ]	Con. Block [ ]	Crawl [ ]	Conc. [ ]	HW [ ]	Pine [ ]	Carp. [ ]	Tile [ ]	Unfinished				
	Cin. Block		Tile		Aluminum [ ]	Masonite [ ]	Riers [ ]	Cin. Blk. [ ]	ATTIC FINISH		INTERIOR CONDITION		FIRE PLACE(S)				
	Steel Frame		Shakes		Storm Doors [ ]	Storm Win. [ ]	Slab [ ]	Brick [ ]	Disappearing Stairs		Gd. [ ]	Fair [ ]	Poor [ ]	VP [ ]			
COMPUTATIONS			EXTERIOR CONDITION		Basement Size		Attic Floor & Stairs		INSULATION		Number		Number Chimneys				
YR.	AGE	DATE	VALUE	DATE	VALUE	Gd. [ ]	Fair [ ]	Poor [ ]	VP [ ]	Basmt. Finish	1/4 [ ]	1/2 [ ]	3/4 [ ]	Full [ ]			
SUMMARY OF BUILDINGS										YR. 1986		YR.		YR.			
Dwelling										Market Value		Market Value		Market Value			
Porch																	
Porch																	
Carport																	
Garage																	
Cent. A/C																	
Basement																	
Bsmt. Finish																	
Attic																	
Fireplace(s)																	
Heating																	
Bath(s)																	
Total																	
Factor																	
Replacement																	
FRONTS ON										LAND VALUE COMPUTATIONS		LAND VALUE COMPUTATIONS		Property and Income Information			
Frontage	Depth	Square Footage	Unit Price	Depth Factor	Front Ft. Rate	TOTAL	Adj.	IS TOTAL APPRAISAL	Unit Price	Depth Factor	Front Ft. Rate	TOTAL	Adj.	IS TOTAL APPRAISAL	Land Cost		
								100							\$		
PROPERTY FACTORS										CLASSIFICATION		ACRES		RATE		ADJ.	
Utilities		Street or Road		Home Site		Woods		100		Home Site		Wasteland		100			
Public Water	Paved														\$		
Public Sewer	Gravel	✓													\$		
Well	Dirt														\$		
Spring	No Road														\$		
Septic System	Curb & Gutter														\$		
U. G. Utilities	Sidewalk														\$		
FRONTAGE TOPOGRAPHY										General Remarks: Topo V Poor							
LEVEL [ ]										SLOPES UP [ ]		SLOPES DOWN [ ]					
LOW [ ]										STEEP UP [ ]		STEEP DOWN [ ]					
														BOARD REVIEW NOTES			