

NAME Belcher, Clayton & Lucille

MAP NO.: _____

X

DESCRIPTION McClure City Lot 1 block 1

DISTRICT ~~Willis~~ Sandhills Hwy; Corp

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEATING
Dwelling	Wood Frame	Wood Siding	Plaster	Comp. Sh.	Year Built 68	Bathrooms 2
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms 7	Basement 2
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories 1	Fireplace
Garage	Brick	C. Block	Panel	Metal	Foundation S	Stoves
Factory	Mill	Stucco	Tile	Tar & Grav.	Floors	Cent. Heat
	Reinf. Conc.				Porch	Floor Fur.
x 24 x 78 = 1872		CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRAISED VALUE
		36				\$ 67400 60000

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$ 66000

LAND

	No. Acres	Value Per Acre	TOTAL	Lots			
				Lot No.	Zoning	Size	Front Ft. Factor
1. Bldg. Site	Lot	FV	3000				
2. Residential							
3. Agricultural							
4. Commercial							
5. Industrial							
6. Mineral Lands							
7. Other							
TOTAL			\$				

Total Appraised Value All Lands \$

Notes: R of 6^{1/2} Just west of Hwy. Should be in Hwy Corp. code. Dimensions given by owner.

RECAPITULATION

	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 3000 2000	\$
Bldgs.	\$ 67400 60000	\$
TOTAL	\$	\$