



NOTES	MAIN BUILDING		EXTERIOR FINISH		GENERAL FEATURES		NUMBER OF ROOMS		INTERIOR FINISH		PLUMBING & HEATING	
	Dwelling		Comp. Sh.		Wood Siding		Yr. Built	Remod.	Bsmt. [ ] 2nd [ ]	Plaster		BATH(S) Full 1/2 Bath(s)
			Slate		Brick		No. Stories		1st [ ] 3rd [ ]	Sheet rock		Modern Bath <input type="checkbox"/> Modern Kitchen <input type="checkbox"/>
			Asbestos		Asb. Wood Shg.		S. Level <input type="checkbox"/> S. Foyer <input type="checkbox"/>		Total No. Bedrooms	Ceciled		Cent. Heat <input type="checkbox"/> A/C <input type="checkbox"/>
	CONSTRUCTION		Metal		Cin. Block <input type="checkbox"/> Stone <input type="checkbox"/>	FOUNDATION		FLOORING		Panel		Fir. or Wall Furnace <input type="checkbox"/> Stove(s) <input type="checkbox"/>
Wood Frame		Tar & Grav.		Stucco <input type="checkbox"/> Con. Block <input type="checkbox"/>	Crawl <input type="checkbox"/> Conc. <input type="checkbox"/>	HW <input type="checkbox"/> Pine <input type="checkbox"/> Carp. <input type="checkbox"/> Tile <input type="checkbox"/>	UNFINISHED				FIREPLACES	
Cin. Block		Tile		Aluminum <input type="checkbox"/> Masonite <input type="checkbox"/>	Riers <input type="checkbox"/> Cin. Blk. <input type="checkbox"/>	ACCESSIONS		INTERIOR CONDITION			Number	
Steel Frame		Shakes		Storm Doors <input type="checkbox"/> Storm Win. <input type="checkbox"/>	Slab <input type="checkbox"/> Brick <input type="checkbox"/>	Disappearing Stairs		Gd. <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> VP <input type="checkbox"/>			Number Chimneys	

COMPUTATIONS		EXTERIOR CONDITION		BASEMENT FINISH		ATTIC FLOOR & STAIRS		INSULATION		STONE	
		Gd. <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> VP <input type="checkbox"/>		Basmt. Finish		1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> Full <input type="checkbox"/>		Attic <input type="checkbox"/> Walls <input type="checkbox"/> FI. <input type="checkbox"/>		Brick [ ] C. Block [ ]	Stone [ ] Metal [ ]

SUMMARY OF BUILDINGS											
Use	YR.	86	YR.	YR.							
Dwelling											
Porch											
Porch											
Carport											
Garage											
Cent. A/C											
Basement											
Basmt. Finish											
Attic											
Fireplace(s)											
Heating											
Bath(s)											
Total											
Factor											
Replacement											

M & L	M & L	MOBILE HOME INFORMATION		Market Value All Improvements		300
DATE	DATE	Owner	Carolyn Smith	Market Value All Land		4308
APRP.	APRP.	Make	Year 75	USE VALUE APPRAISAL RECAP		4608
DATE	DATE	Size	12x60	Agriculture		
CLASSIFICATION	ZONING	Not Home <input checked="" type="checkbox"/> Time		Hort.		
9-17-85	2	AM <input type="checkbox"/> PM <input checked="" type="checkbox"/>		Forest		
		INFORMATION BY		Open Space		
				Totals		

FRONTS ON				LAND VALUE COMPUTATIONS				LAND VALUE COMPUTATIONS			

PROPERTY FACTORS				CLASSIFICATION				CLASSIFICATION			
Public Water	Paved			Home Site	1	400	2500	Home Site			
Public Sewer	Gravel				4.52	1808					
Well	Dirt										
Spring	No Road										
Septic System	Curb & Gutter			Wasteland				Wasteland			
U. G. Utilities	Sidewalk				5.52		4308				

FRONTAGE TOPOGRAPHY			General Remarks:		
LEVEL <input type="checkbox"/>	SLOPES UP <input type="checkbox"/>	SLOPES DOWN <input type="checkbox"/>			
LOW <input type="checkbox"/>	STEEP UP <input type="checkbox"/>	STEEP DOWN <input type="checkbox"/>			

BOARD REVIEW NOTES