

NAME Adkins, Harold D. & Gayle  
 DESCRIPTION Partlcr 1 lot MULLIN RDC

MAP NO.: \_\_\_\_\_  
 DISTRICT Willis

BLOCK \_\_\_\_\_ HOUSE NO. \_\_\_\_\_

**MAIN BUILDING**

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEAT & COOLING	
Dwelling	<input checked="" type="checkbox"/> Wood Frame	<input checked="" type="checkbox"/> Wood Siding	Plaster	Comp. Sh.	<input checked="" type="checkbox"/> Year Built	Bathrooms	
Store	Steel Frame	Brick	Wall Board	Slate	No. Rooms	Basement	
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories	Fireplace	
Garage	Brick	C. Block	Panel	Metal	Foundation	Stoves	
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors	Cent. Heat	
	Reinf. Conc.				Porch	Floor Fur.	
X	X	=	CU. FT. SQ. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRaised VALU <u>3000 3000</u>

**OUT BUILDINGS**

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$ 3000

**LAND**

USE	No. Acres	Value Per Acre	TOTAL	Lots				
				Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Tillable				<u>lot</u>				<u>400</u>
2. Pasture								
3. Timber								
4. Cut Over								
5. Marsh - Mountain								
6. Commercial								
7. Industrial								
8. Mineral								
TOTALS			\$					

Total Appraised Value All Lands \$ 400

Notes:

**BUILDING PERMITS**

No.	Type	Date	% of Comp	Final A.

**RECAPITULATION**

	APPRAISED VALUE	ASSESSED VALUE
Land	\$ <u>400</u>	\$ <u>40</u>
Bldgs.	\$ <u>3000</u>	\$ <u>300</u>
TOTAL	\$ <u>3400</u>	\$ <u>340</u>

