

NAME Borders, J. Mike & Carol

MAP NO.: _____

DESCRIPTION Hill top 24.03

DISTRICT Willis

MAIN BUILDING												
USE	CONSTRUCTION		EXTERIOR FINISH		INTERIOR FINISH		ROOFING	GENERAL FEATURES		PLUMBING & HEATING		
Dwelling	✓	Wood Frame	✓	Wood Siding	Plaster	✓	Comp. Sh.	✓	Year Built	53	Bathrooms	Three ✓
Store		Steel Frame		Brick	Wall Board		Slate		No. Rooms	9	Basement	Furn. see Room
Service Station		File-C. Blk		Asb-wood shing.	Ceiled		Asbestos		No. Stories	1 1/2	Fireplace	
Garage		Brick	✓	C. Block	Panel		Metal		Foundation	S	Stoves	
Factory		Mill		Stucco	Tile		Tar&Grav.		Floors		Cent. Heat	✓ Coal F. (HV)
		Reinf. Conc.							Porch	Tile	Floor Fur.	
17 x 18 + 38 x 60 = 2586				CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence		APPRAISED VALUE			
				24	=	=			\$ 62100			

OUT BUILDINGS					
USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS	
Garage	✓	C/B			FV 5000 4000
Barn					
Chicken House					
Tenant House					
Misc. Bldg.					

Total Appraised Value All Improvements \$ ~~67100~~ 66100

LAND				Lots				
	No. Acres	Value Per Acre	TOTAL	Lot No.	Zoning	Size	Front Ft. Factor	Appraised Value
1. Bldg. Site	1	FV	3000 4000					
2. Residential								
3. Agricultural	23.03	340 250	6900 5800					
4. Commercial								
5. Industrial								
6. Mineral Lands								
7. Other								
TOTAL			\$ 9900 9800					

Total Appraised Value All Lands \$

Notes: 1/2 of 1/2 of land to [unclear]

RECAPITULATION		
	APPRAISED VALUE	ASSESSED VALUE
Land	\$ 9900 9800	\$
Bldgs.	\$ 67100 66100	\$
TOTAL	\$ 77000 75900	\$