

NAME Cumbo, Clayton & Wife

MAP NO.: _____

DESCRIPTION Tantrough Br. 13.67

DISTRICT ~~SAND LICK SAND LICK~~

BLOCK _____ HOUSE NO. _____

MAIN BUILDING

USE	CONSTRUCTION	EXTERIOR FINISH	INTERIOR FINISH	ROOFING	GENERAL FEATURES	PLUMBING & HEAT	
Dwelling	✓ Wood Frame	✓ Wood Siding	Plaster	Comp. Sh.	✓ Year Built	Bathrooms <u>No</u>	
Store	Steel Frame	Brick <u>siding</u>	Wall Board	Slate	No. Rooms <u>4</u>	Basement <u>1/2</u>	
Service Station	Tile-C. Blk	Asb-wood shing.	Ceiled	Asbestos	No. Stories <u>1</u>	Fireplace	
Garage	Brick	C. Block	Panel	Metal	Foundation <u>S</u>	Stoves ✓	
Factory	Mill	Stucco	Tile	Tar&Grav.	Floors <u>P</u>	Cent. Heat	
	Reinf. Conc.				Porch ✓	Floor Fur.	
X	X	=	CU. FT.	UNIT FACTOR	TOTAL	Physical Depreciation or Obsolescence	APPRaised VALU
			SQ. FT.		=	-	<u>\$ 800 100</u>

OUT BUILDINGS

USE	CONSTRUCTION	CONDITION	SIZE	GEN. REMARKS
Garage				
Barn				
Chicken House				
Tenant House				
Misc. Bldg.				

Total Appraised Value All Improvements \$ 1000

LAND

USE	No. Acres	Value Per Acre	TOTAL	Lots				
				Lot No.	Zoning	Size	Front Ft. Factor	Appr
1. Tillable								
2. Pasture								
3. Timber								
4. Cut Over								
5. Marsh - Mountain								
6. Commercial								
7. Industrial								
8. Mineral								
TOTALS	<u>13.67</u>		<u>600</u>					

Total Appraised Value All Lands \$ 600

Notes: Bike school on Hwy 614
2 - from church

BUILDING PERMITS

No.	Type	Date	% of Comp	Final A.

RECAPITULATION

	APPRAISED VALUE	ASSESSED
Land	\$ 600	\$ 60
Bldgs.	\$ 1000	\$ 100
TOTAL	\$ 1600	\$ 160

